Instruction manual WS 9120

FEATURES:
Measuring temperature range: 0 ~ 50 ℃ (32℉ - 122℉)
Measuring humidity range: 20% ~ 99%
Resolution: 1°C / 1%
Power: 2 x Micro /AAA (not included)

OPERATION:
Press MODE one time to view calendar
Press MODE one more time to view alarm time

SETTING THE TIME
Press and hold MODE for 3 seconds to enter the time setting mode.
The hour digits are blinking and can be set by pressing UP or DOWN for setting hour.

Press MODE again:
The minute digits are blinking and can be set by pressing UP or DOWN for setting minute.

SETTING THE CALENDAR
Press MODE to the view calendar
Press MODE hold for 3 seconds to enter the calendar setting mode.
The year digits are blinking and can be set by pressing UP or DOWN for setting year.
Press MODE again:
The month digits are blinking and can be set by pressing UP or DOWN for setting month.
Press MODE again:
The day digits are blinking and can be set by pressing UP or DOWN for setting day.

SETTING THE ALARM
Press MODE to view the alarm time
Press MODE hold for 3 seconds to enter the alarm setting mode.
The hour digits are blinking and can be set by pressing UP or DOWN for setting hour.
Press MODE again:
The minute digits are blinking and can be set by pressing UP or DOWN for setting minute.

ALARM ON/OFF
Press UP to turn alarm on/off.

MAX / MIN
Press MAX/MIN to view MAX temperature and humidity record.
Press MAX/MIN again to view MIN temperature and humidity record.

12/24 FORMAT HOUR
At the time mode, Press UP for 3 seconds to switch 12 or 24 format hour time display.

TEMPERATURE DISPLAY FORMAT
Press DOWN to switch ℃/℉ display.

SNOOZE/LIGHT
In alarm to press SNZ/LIGHT for snooze mode.
Press SNZ/LIGHT to turn on light.