

User's Manual

WA 1030 – Bath thermometer

Installation

Put the bath thermometer in your bath tub, filled with water.

Function

In the transparent glass tube is the measuring liquid, which expands depending on the temperature and displays value on the measuring scale accordingly. This value represents the current temperature and is displayed in ° C.

Specifications

Measuring range: +10°C to +50°C

Dimensions (BxDxH): 60 x 14 x 150 mm