

User's Manual

WA 1040 – Indoor and outdoor thermometer

Installation

Wall mounting can be achieved by use of the hole in the upper part of the thermometer.

Function

In the transparent glass tube is the measuring liquid, which expands depending on the temperature and displays value on the measuring scale accordingly. This value represents the current temperature and is displayed in ° C.

Specifications

Measuring range: -20°C to +50°C

Dimensions (BxDxH): 50 x 15 x 210 mm