

User's Manual

WA 1020 – Fridge thermometer

Installation

Mounting in the fridge can be achieved by use of the hook on the upper part of the thermometer.

Function

In the transparent glass tube is the measuring liquid, which expands depending on the temperature and displays value on the measuring scale accordingly. This value represents the current temperature and is displayed in ° C.

Specifications

Measuring range: -40°C to +40°C

Dimensions (BxDxH): 24 x 9 x 155 mm