



# KW 100 - ELECTRONIC SCALE INSTRUCTIONS

## BATTERIES




3 x AAA Micro 1.5V

## TO REPLACE BATTERIES




Ensure +/- terminals are correct way round.

## TO SWITCH ON




Press and release **ON/OFF** button.  
**8888** appears on display.  
Wait until display shows **0**.

## PRESS TO CONVERT WEIGHT UNITS




Press **g/LB** button (on unit bottom) to convert between metric and imperial units.

## TO ADD & WEIGH



To weigh several different ingredients in one bowl,  
press **TARE** to reset the display between each ingredient.

## AUTO SWITCH OFF



Auto switch-off occurs if display show **0** for 1 minute  
or shows the same weight reading for 1 minute.

## WARNING

0-Ld

Weight overload



Replace batteries

## CLOCK INSTRUCTIONS

- 1) Insert 1 x PC "AG13" type battery in clock.
- 2) Set time by turning knob on movement.
- 3) Replace battery once a year even if clock is still running.
- 4) Remove battery when clock is not in use.