

User's Manual

WA 1010 – Window thermometer

Installation

Remove the protective foil from each of the adhesive pads located on each corner of the thermometer and press the adhesive pads against the window to install the thermometer at the window.

Function

The hand moves along the measuring scale depending on the temperature and points towards a scale value. This value represents the current temperature and is displayed in ° C.

Specifications

Measuring range: -50°C to +50°C

Dimensions (BxDxH): 75 x 21 x 75 mm