

## **User's Manual**

### **WA 1015 – Universal thermometer**

#### **Installation**

The design of the universal thermometer allows an easy standing on flat surfaces.

#### **Function**

The hand moves along the measuring scale depending on the temperature and points towards a scale value. This value represents the current temperature and is displayed in °C and °F.

#### **Specifications**

Measuring range: -10°C to +50°C; +20°F to +120°F

Dimensions (BxDxH): 70 x 22 x 55 mm